

CJ-Pro  
Renewables Signs  
Catalogue





Access above  
this level requires  
Work at Height &  
Rescue Training -  
Wind Turbines  
(RUK/GWO)

RECJ001



Rotor lock to  
be applied  
before hub  
access

RECJ002




Stop wind  
turbine before  
climbing

RECJ003



Safety harness  
must be worn

RECJ004



**Danger**  
falling ice  
from turbines

RECJ005



**Danger  
of  
death**

RECJ006



Solar PV  
Module  
**DANGER**  
Contains live parts  
during daylight

RECJ007



**Cable trip  
hazard**

RECJ008



**CHARGING  
POINT**



RECJ009



**CHARGING  
POINT**



RECJ010



**CHARGING  
POINT**




RECJ011



RECJ012




RECJ013




RECJ014




RECJ015



RECJ016




RECJ017




RECJ018




RECJ019




RECJ020




RECJ021



RECJ022



RECJ023



RECJ024




RECJ025




RECJ026



RECJ027



RECJ028



RECJ1029